

7-15-82  
12.3.8 v.3



Acts 4.12

**DIVISION OF**  
**SDNyers** **TRANSFORMER**  
**CONSULTANTS**

Suite 10, 26062 Eden Landing Rd.  
Hayward, California  
Phone: (415) 783-7744  
Toll Free: (800) 972-5940  
Outside Calif. (800) 227-0637

July 15, 1982

Lone Star Cement Company  
3801 East Marginal Way  
Seattle, Washington 98134

Attn: Mr. Paul Burton

Gentlemen:

Here are the results of the transformer oils recently tested at your plant. Any previous test results should be replaced by this current data.

FURTHER WORK IS REQUIRED on some of these transformers. We are recommending that the work on the following transformers be done by YOUR PERSONNEL:

<u>TC#</u>	<u>Location</u>	<u>MFG</u>	<u>S/N</u>	<u>KVA</u>	<u>GALLONS</u>
17	Raw Mill	West	1606137	15	9
18	Raw Mill	West	1606070	15	9
19	Raw Mill	West	1606715	15	9

We will be submitting a proposal for corrective action on the remaining transformers that require servicing.

We will contact you for an appointment to discuss this proposal with your personnel responsible for decision relative to the recommended corrective action.

If you have any questions, please feel free to contact us at any time.

Sincerely,

Fred Shephard  
Regional MTL Supervisor

FS/dr  
Test No:82-50105

**USEPA SF**



**1261049**

AGC2F000172